

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office SP
Lease No. 080212
Unit Malco-Copple

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

APR 25 1958

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Sandoll Frac.</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 25, 1958


Well No. 10 is located 300 ft. from TS line and 1900 ft. from EW line of sec. 6
SW SE/4 Section 6 30-N 15-W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde-Gallup Saa Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5450 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-24-58 Total Depth 2993'.
 Cannon fractured Gallup openhole interval 2861' - 2993' with 12,600 gallons oil and 15,000# sand. Breakdown pressure 1150#, Max. TP-1125#, Avg. TP-900#. Injection Rate 43.0 bbl./min.
 Flush 2940 gallons.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Products Company

Address Post Office Box 1565
Farmington, New Mexico

ORIGINAL SIGNED BY: JOSEPH E. KREI
 By _____

Title Petroleum Engineer