


30-045-09871




UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No. 1-149-74-764

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sent. 2, _____, 1952

Well No. Navajo 1 is located 100 ft. from S line and 660 ft. from E line of sec. 4

30 Sec. 4 (1/4 Sec. and Sec. No.) 30N (Twp.) 14W (Range) New Mexico (Meridian)
Wilcox (Field) San Juan Co. (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. Will be furnished later

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill 1 1/2 inch test.
Set 1 3/8 inch casing 6500 feet cement to surface
If productive run 1 1/2 inch casing as follows:
From bottom 20 feet to 6500 feet. 50 lbs. cas.
1100 feet 1 1/2 inch casing. 210 feet 1 1/2 inch casing at bottom
cemented with 300 sacks.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum Co.

Address Butte, Montana

By [Signature]

Title District Mgr.

