

(SUBMIT IN TRIPLICATE)

Indian Agency NavajoUNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. 14-20-003-2021

## SUNDRY NOTICES AND REPORTS ON WELLS

|   |  |  |  |
|---|--|--|--|
| NOTICE OF INTENTION TO DRILL                  |  | SUBSEQUENT REPORT OF WATER SHUT-OFF        |  |
| NOTICE OF INTENTION TO CHANGE PLANS           |  | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |  |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF    |  | SUBSEQUENT REPORT OF ALTERING CASING       |  |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL |  | SUBSEQUENT REPORT OF REDRILLING OR REPAIR  |  |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE       |  | SUBSEQUENT REPORT OF ABANDONMENT           |  |
| NOTICE OF INTENTION TO PULL OR ALTER CASING   |  | SUPPLEMENTARY WELL HISTORY                 |  |
| NOTICE OF INTENTION TO ABANDON WELL           |  |  |  |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

1-23-02, 19\_\_

Well No. Chuck #1 is located 990 ft. from N line and 990 ft. from E line of sec. 6

SE 6 30N 17W N.M.P.  
(34 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5003 ft. ±1

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6 3/4 hole to 30'. Set 52 casing w/15 sax.  
Drilled 4 3/4 hole to 508', tested Gallup - nondeveloped.  
Plugged bottom of hole w/20 sax cement and 10 sax  
cement in surface. Set marker.

RECEIVED  
JAN 23 1962  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEX.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. L. BaylessAddress Box 1541  
Farmington, N. M.By R. L. Bayless  
Title \_\_\_\_\_

