

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 43-2350.4
Approval Number 12-21-00.

Indian Agency

Allottee

Lease No. **14-2-402-733**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED

OCT 23 1958

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 7, 1958

WELL NO. 2 is located **1200** ft. from **N** line and **320** ft. from **E** line of sec. **8**
1/4 Section 8 (1/4 Sec. and Sec. No.)
20N (Twp.) **10E** (Range) **10W** (Meridian)
WINDMILL CANYON (Field) **SAN JUAN** (County or Subdivision) **NEW MEXICO** (State or Territory)

The elevation of the derrick floor above sea level is **3315** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10-4-58 Set 3 1/2" 120 J-55 SS Casing at 1239' w/100 on cement containing 2% SE Gel & 1/2% Fluor Seal.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **WINDMILL CANYON, INC.**

Address **720 N. MAIN**

FARMINGTON, NEW MEXICO

ORIGINAL SIGNED BY

N. B. GOVE

By

N. B. GOVE

Title

MANAGER

4-10-60


RECEIVED

607 4 1959

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C.

2

RECEIVED
FBI
APR 10 1960



APR 10 1960

APR 10 1960

APR 10 1960

APR 10 1960