
Budget Bureau No. 42-R358.4. Approval expires 12-31-60.



(SUBMIT IN TRIPLICATE)

Land Office SF 080212-A Lease No. Malco Copple Unit

400

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF
	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALI'ER CASING.	SUPPLEMENTARY WELL HISTORY.
NOTICE OF INTENTION TO ABANDON WELL	300000000000000000000000000000000000000
(INDICATE ABOVE BY CHECK MARK)	20011 0
The state of the s	ATURE OF REPORT, NOTICE, OR OTHER DATA)
	August 31 , 19.59
ell No. 1-A is located 660 ft. from	$\left\{\begin{array}{c} N \\ N \end{array}\right\}$ line and 1980 ft. from $\left\{\begin{array}{c} R \\ W \end{array}\right\}$ line of sec.
NE NW/4 Section 4 30N 15W	
(½ Sec. and Sec. No.) (Twp.) (Ra	NWIPM mge) (Meridian)
Verde-Gallup San Juan	New Mexico
(Field) (County or Su	ibdivision) (State or Territory)
ne elevation of the derrick floor above sea level	is 5452 ft.
	OF WORK
ate names of and expected depths to objective sands; show sizes, w ing points, and all other	veights, and lengths of proposed casings; indicate mudding jobs, cement- r important proposed work)
Spud Date: August 21, 1959. August 22,	1959 Total Depth 135*.
Ran 3 joints, 10-3/4", 28.60#, S. W 125 sacks regular coment, 3% CaCl	V. Casing (122.04') set at 130.04' with lack circulated to surface.
123 sacks regular cement, 3% CaCl	V. Casing (122.04') set at 130.04' with la circulated to surface.
Ran 3 joints, 10-3/4", 28.60#, 5.W 125 sacks regular cement, 3% CaCl Held 500#/30 Minutes.	V. Casing (122.04') set at 130.04' with l2 circulated to surface.
123 sacks regular cement, 3% CaCl	V. Casing (122.04') set at 130.04' with la circulated to surface.
123 sacks regular cement, 3% CaCl	V. Casing (122.04') set at 130.04' with 12 circulated to surface.
123 sacks regular cement, 3% CaCl	V. Casing (122.04') set at 130.04' with la circulated to surface.
Held 500 #/30 Minutes.	12 circulated to surface.
Held 500 #/30 Minutes. Held 500 #/30 Minutes.	ing by the Geological Survey before extensions may be commenced.
Held 500 #/30 Minutes. Held 500 #/30 Minutes.	ing by the Geological Survey before extensions may be commenced.
Held 500 #/30 Minutes.	ing by the Geological Survey before Clientical may be commenced.
Held 500*/30 Minutes. I understand that this plan of work must receive approval in writing mpany El Paso Natural Gas Product	ing by the Geological Survey before extensions may be commenced.