
Denny S. Fourt DEPUTY OIL & GAS INSPECTOR

DEC 0 2 1997

Approval

Meter Number:72129
Location Name:BLANCO #11
Location:TN-31 RG-08
SC-26 UL-G
2 - Federal
NMOCD Zone:OUTSIDE
Hazard Ranking Score:00



RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN



This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10^{-9} to 10^{-13} cm/sec Shale 10^{-12} to 10^{-16} cm/sec Clay 10^{-12} to 10^{-15} cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 72129 Location: BLANCO # 1\ Operator #: 7035 Operator Name: PHILLIPS P/L District: BLOOMFIELD Coordinates: Letter: 6 Section 26 Township: 31 Range: 8 Or Latitude Longitude Pit Type: Dehydrator X Location Drip: Line Drip: Other: Site Assessment Date: 5.7.94 Area: 10 Run: 63
SITE ASSESSMENT	NMOCD Zone: Cand Type: BLM
REMARAS	Remarks: Two PITS ON LOCATION WILL CLOSE ONLY ONE PIT IS DRY. LOCATION IS ON A MESA ABOUE NAVADO LAKE, REDLINE AND TOPO CONFIRMED LOCATION TO BE OUTSIDE THE V-Z. PUSH IN

		=				
LOCATION	ORIGINAL PIT LOCATION					
	Original Pit : a) Degrees from North <u>284°</u> Footage from Wellhead <u>72′</u>					
	b) Length : <u>30'</u> Width : <u>20'</u> Depth : <u>4'</u>	_				
	K					
pit pit						
ORIGINAL	Liver of San					
ORIG						
	30' 20'	!				
		_				
	Remarks:					
	ENO DUMP	- -				
REMARKS		-				
		-				
		_				
		- -				
		-				
		_				
	Completed By:					
	todal Thampson 5.7.94	į,				
	Signature Date					

FIELD IT REMEDIATION/CLOSUR FORM

GENERAL	Meter: 72/29 Location: Blanco # 1/ Coordinates: Letter: G Section 26 Township: 3/ Range: 8 Or Latitude Longitude Date Started: 6-2-94 Area: 10 Run: 63
FIELD OBSERVATIONS	Sample Number(s): $VW170$ Sample Depth: $12'$ Feet Final PID Reading 12 PID Reading Depth $12'$ Feet Yes No Groundwater Encountered \square (1) \square (2) Approximate Depth \square Feet
CLOSURE	Remediation Method: Excavation
	Envirotech (1) (3) Tierra Other Facility (2) Name: Pit Closure Date: 6-2-91-1 Pit Closed By: 1362
REMARKS	Remarks: Live Maskers
	Signature of Specialist: Ude Way (SP3191) 04/07/94

-2-



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

					_		
r	Field	ID	Lab ID				
SAMPLE NUMBER:	SAMPLE NUMBER: Vw 17 0 MTR CODE SITE NAME: フュルタ			945342 N/A			
MTR CODE SITE NAME:							
SAMPLE DATE TIME (Hrs):	4-2-94		1100				
SAMPLED BY:	N/A						
DATE OF TPH EXT. ANAL.: (2-6-94		6					
DATE OF BTEX EXT. ANAL.:	N/A		~/				
TYPE DESCRIPTION:	∨	V G		Frey Sand & Clay			
REMARKS:		RESULTS					
		NESUL 15					
PARAMETER	RESULT	UNITS	QUALIFIERS DF Q M(g) V			V(ml)	
BENZENE		MG/KG					
TOLUENE		MG/KG					
ETHYL BENZENE		MG/KG					
TOTAL XYLENES		MG/KG					
TOTAL BTEX		MG/KG					
TPH (418.1)	<10	MG/KG			2.13	25	
HEADSPACE PID	12	PPM					
PERCENT SOLIDS	90.8	%		· - · · · - · · · - · · · · · · · · · ·		····	
e Surrogate Recovery was at	- TPH is by EPA Method 4	18.1 and BTEX is by EPA % for this samp		was accep	table.		

DF = Dilution Factor Used

Approved By: John Jara.

Test Method for

Oil and Grease and Petroleum Hydrocarbons
in Water and Soil

94/06/06 13:59

Sample identification 745342

inithal mass of sample, g

Valume of sample after extraction, ml $13.000\,$

Patroleum hydrocarbons, ppm -159,293

Net absorbance of bydrtcarbons (2930 cm-1)

