DEPUTY OIL & GAS INSPECTOR

DEC 0 2 1997

tyron cel

Meter Number: 70517
Location Name: KERNAGHAN B #2
Location: TN-31 RG-08
SC-28 UL-H
2 - Federal

NMOCD Zone: OUTSIDE Hazard Ranking Score: 00

DECEIVED N APR 1 4 1897

OIL COM. DIV.

# RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone  $10^{-9}$  to  $10^{-13}$  cm/sec Shale  $10^{-12}$  to  $10^{-16}$  cm/sec Clay  $10^{-12}$  to  $10^{-15}$  cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

#### FIELD PIT SITE ASSESSMENT FORM PASOFIELD SERVICE

GENERAL	Meter: 70517 Location: KERNAGHAN 8 # 2  Operator #: 0203 Operator Name: Amoco P/L District: Bloomfield  Coordinates: Letter: H Section 28 Township: 31 Range: 8  Or Latitude Longitude  Pit Type: Dehydrator X Location Drip: Line Drip: Other:  Site Assessment Date: 5:24.94 Area: 0 Run: 32							
SITE ASSESSMENT	NMOCD Zone:       Land Type:       BLM       ☒ (1)         (From NMOCD       State       ☐ (2)         Maps)       Inside       ☐ (1)       Fee       ☐ (3)         Outside       ☒ (2)       Indian       ☐         Depth to Groundwater       ☐ (1)       ☐ (1)         Less Than 50 Feet (20 points)       ☐ (1)         50 Ft to 99 Ft (10 points)       ☐ (2)         Greater Than 100 Ft (0 points)       ☒ (3)							
	Wellhead Protection Area:  Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points)							
	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) (1) 200 Ft to 1000 Ft (10 points) (2) Greater Than 1000 Ft (0 points) (3) Name of Surface Water Body							
	(Surface Water Body : Perennial Rivers,Major Wash,Streams,Creeks, Irrigation Canals,Ditches,Lakes,Ponds) Distance to Nearest Ephemeral Stream □ (1) < 100'(Navajo Pits Only) □ (2) > 100'							
	TOTAL HAZARD RANKING SCORE: POINTS							
REMARKS	Remarks: Two Pits on Location, Pit is Dry, will close only one. Location is on Pump Mesa. Redline And Topo confirmed Location							
ЕМА	IS OUTSIDE V.Z.							
R	Pusit-In.							

İ	ORIGINAL PIT LOCATION
	Original Pit : a) Degrees from North 139° Footage from Wellhead <u>85'</u>
LOCATION	b) Length : Width : Depth :
	N N
PIT	
ORIGINAL PIT LOCATION	Tugo.
	MECHENO
	\sqrt{\sq}\}}}\sqrt{\sq}}}}}}\sqrt{\sq}}}}}}}}}}}}\signt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}
	17'
	12
	Remarks :
	TOOK PICTURES AT 1:56 P.M.
	END DUMP
S	
REMARKS	
ЗEМ	
1	
,	
	Completed By:
:	5.24.94
	Signature Date

## FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 70517 Location: KERNAGHAN 3 <sup>#</sup> Z  Coordinates: Letter: H Section 28 Township: 3 Range: 8  Or Latitude Longitude  Date Started: 11/18/94 Run: 10 32
FIELD OBSERVATIONS	Sample Number(s): KD 368  Sample Depth: Feet  Final PID Reading PID Reading Depth Feet  Yes No  Groundwater Encountered
CLOSURE	Remediation Method:  Excavation  Onsite Bioremediation  Backfill Pit Without Excavation  Soil Disposition:  Envirotech  Other Facility  Name:  Pit Closure Date: 11/18/99  Pit Closed By: BET
REMARKS	Remarks: Dug test Hoke to 12', Took sid Sample, Closed pit.  Signature of Specialist: Why January (SP3191) 03/16/94



## FIELD SERVICES LABORATORY ANALYTICAL REPORT

### PIT CLOSURE PROJECT - Soil Samples Outside the GWV Zone

	SAMPLE	IDENTIFICA	TION				
	Field		Lab ID				
SAMPLE NUMBER:	KO 36	946487					
MTR CODE   SITE NAME:	70517		N/A				
SAMPLE DATE   TIME (Hrs):	11-18-6	ଅୟର ୦					
SAMPLED BY:							
DATE OF TPH EXT.   ANAL.:	DATE OF TPH EXT.   ANAL.:			11-22-94			
DATE OF BTEX EXT.   ANAL.:	NA		N/M	····			
TYPE   DESCRIPTION:	٧G	<u> </u>					
REMARKS:		DECLII TO					
		RESULTS					
PARAMETER	RESULT UNITS		QUALIFIERS DF Q		ERS M(g)		
TPH (418.1)	2640	MG/KG			2.09	28	
HEADSPACE PID	784	PPM					
PERCENT SOLIDS	92.8	%					
		TPH is by EPA Metho	d 418.1				
Narrative:							
DF = Dilution Factor Used							
Approved By:	Date:	12-6-9	· ¥				

Test Method for Oil and Grease and Petroleum Hydrocarbons in Water and Soil

Perkin-Elmer Model 1600 FT-IR Analysis Report \*

10:49 94/11/22

Sample identification 946487

Initial mass of secolar 9

Yolume of sample eiter extraction, ml

Potroleca bydrodurbora, 200 2. M. CAS Mat sbacrbunda of h. bradarhona (1930 om -1) 5. 747

