Form 9-331 (May 1963) UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other Instructions on re- GEOLOGICAL SURVEY			Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. SF 073386
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME
EL PASO NATURAL GAS COMPANY 3. ADDRESS OF OPERATOR			8. FARM OR LEASE NAME. Riddle "D" 9. WELL NO.
Box 990, Farmington, New Mexico 87401 4. Location of Well (Report location clearly and in accordance with any State requirements. See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT
At surface 1790 1705 S, 890 W., Sec. 22 T 31N, R 9W			Blanco MV 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA SW. Sec. 22, 31, 9
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, R	RT, GR, etc.)	12. COUNTY OF PARISH 13. STATE San Juan N.M.
	propriate Box To Indicate Na	ture of Notice, Report, or C	Other Data
NOTICE OF INTEN	rion to:	SUBSEQ	UENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	BEPAIRING WELL
FRACTURE TREAT	SULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
	ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENT*
	CHANGE PLANS	(Other) Ran sucker	rods & Pump X of multiple completion on Well
(Other)	Particology (Closely state all particular	Completion or Recomp	letion Report and Log form.)
Pulled tubing and found 4893.03' (1 hole). Repand mandrel from bottom of tubing then 173 jts. 5/8" rods and 85 3/4" repump.	d perforated joints at placed these with non- n. Ran tubing Baker A tubing back into hol	t 4546.42' (11 holes -perforated joints. Anchor-catcher and p	Removed swab cups erf joint on bottom
18. I hereby certify that the foregoing is			
signed Thank	TITLE Prod	luction Engineer	DATE March 9, 1972
(This space for Federal or State office			
CONDITIONS OF APPROVAL, IF A	NY:		DATE OF THE STATE