



(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078505

Unit W/2 Sec. 14, T. 31N,
R. 9W, San Juan Cty., N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
JUL 15 1968

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 24, 1968

Well No. 6 Seymour is located 790 ft. from [N] line and 1035 ft. from [W] line of sec. 14.

SW/4, SE/4, 14
(1/4 Sec. and Sec. No.)

31N
(Twp.)

9W
(Range)

N.M.P.M.
(Meridian)

Blanco-Mesa Verde
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6215 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

We Propose To: Repair 7" casing damage at approx. depth 2692-2698' & cement squeeze this section, Clean out hole to present T.D. (5450') and deepen well 230' to 5685'. Run approx 1038' of 4" flush joint liner and cement. Perf. and frac well in an effort to stimulate production.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SOUTHERN NATURAL GAS COMPANY

Address P.O. Box 358

Farmington, New Mexico

By Vernon J. Lowe
Title Drilling Superintendent

THE NEW YORK PUBLIC LIBRARY

18

24