

Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078438  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Pritchard May 2 \_\_\_\_\_, 59  
1 990 ft. from N line and 340 ft. from E line of sec. 1  
Well No. \_\_\_\_\_ is located \_\_\_\_\_ ft. from S line and \_\_\_\_\_ ft. from W line of sec. 1  
S.W. 1/4 Sec. 1 8-30-N R-9-W 114PM  
Wildcat \_\_\_\_\_  
(1/4 Sec. and Sec. No.) Santa Juan (Range) \_\_\_\_\_ (Meridian)  
New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5888 ft. G. L. (Alt.)

DETAILS OF WORK

Run 5 in. of 10 5/8 in. casing for surface pipe; total pipe  
in well 235' set at 242' (KB) with 200 sacks of regular cement and  
circulated to surface. Prior to drilling out plug casing was tested  
with 500# pressure for 30 min. with no drop; after drilling out  
cement, rotary was stopped and fluid level in casing was measured  
for any drop or use; fluid level remained stationary.

(Well spudded 5:00 a.m. 4/28/51)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.  
Edin Oil Corporation

Company 305 W. Main  
Address Farmington, New Mexico

By J. Maxwell  
Title Field Supt.