1 File

Form Approved. Budget Bureau No. 42-R1424

| orm 9–331  | 6 MMS, Fmn 1 File  |                                      | Budget Bureau No. 42-R1424   |
|--|--|--------------------------------------|--|
| ec. 1973   | UNITED STATES  | ١,,, [                               | 5. LEASE<br>030555 - A   |
|  | DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY  | 1/14                                 | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME   |
| SUNDRY   | Y NOTICES AND REPORTS ON WEL   | LS<br>different                      | 7. UNIT AGREEMENT NAME   |
| o not use this<br>servoir. Use Fo  | form for proposals to drill or to deepen or plug back to a corm 3-331-C for such proposals.)   |                                      | 8. FARM OR LEASE NAME<br>Mexico Federal "L"  |
| 1. oil   | gas other other  |                                      | 9. WELL NO.  |
| 2. NAME OF   | F OPERATOR<br>UGAN PRODUCTION CORP.  |                                      | 10. FIELD OR WILDCAT NAME<br>Basin Dakota  |
| Þ  | OF OPERATOR O Box 208, Farmington, NM 87401  |                                      | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA   |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 990' FSL - 1650' FWL AT TOP PROD. INTERVAL: |  |                                      | Sec 10 T30N R13W  12. COUNTY OR PARISH 13. STATE NM  |
|  |  |                                      |  |
| 16. CHECK /  | APPROPRIATE BOX TO INDICATE NATURE OF N<br>, OR OTHER DATA   | NOTICE,                              | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 5703' GL; 5713' RKB  |
| DEQUEST FO   | OR APPROVAL TO: SUBSEQUENT REPORT  | OF:                                  | 0,00   |
| TEST WATER   | R SHUT-OFF 닠 님;;;;   |                                      |  |
| FRACTURE T   | TREAT  | han IV k                             | (NOTE: Report results of multiple completion or zon  |
| REPAIR WEL   | L 및 TH SEPT  | 1 4 198                              | change on Form 9–330.)   |
| PULL OR AL   | LTER CASING L  |                                      |  |
| CHANGE ZO  | NES 📗  |                                      |  |
| ABANDON*   |  |                                      | abilitation  |
| - DECCO!   | IBE PROPOSED OR COMPLETED OPERATIONS (Clarge estimated date of starting any proposed work. I red and true vertical depths for all markers and zone | learly sta<br>f well is<br>es pertin | ate all pertinent details, and give pertinent date<br>directionally drilled, give subsurface locations ar<br>ent to this work.)* |
|  | 1. No P & A marker on this locat   | ion.                                 | wall mad mer RIM specifications  |
|  | 2. Filled the pits and recontour   | eu the                               | e well pad per BLM specifications  |
|  |  | x #3                                 | 9-8-82. <b>RFT</b>   |
|  | 4. Reseeded the pad with seed mi   |                                      |  |
|  |  |                                      | OIL CORL COM<br>DIST 30M   |
|  | Location is now ready for inspect  | tion.                                | \" CON 8 1982  |
|  |  |                                      | 0157 500   |
|  |  |                                      |  |
|  | e Safety Valve: Manu. and Type   |                                      | Set @  |
| Subsurfac  | e Safety Valve: Manu. and Type   |                                      |  |
| 18. I here   | ACCEPTED FOR RECORD  | ent                                  | 9-13-82  |
| SIGNED 🔏   | Sperman E. Dugantile   | al or State                          | e office use)  |
|  | ACCEPTED FOR RECORD  | ai 0i 3i3ti                          | DATE   |
| APPROVED   | BY THE THE STATE OF APPROVAL, IF ANY:  |                                      |  |
| CONDITION  | • 5 • 6 • 6 • 6 • 6  |                                      |  |

SEP 15 1982