State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

API # (assigned by OCD)
30-045-20133

1. **Type of Well**
GAS

5. **Lease Number**

6. **State Oil&Gas Lease #**
E-3149

2. **Name of Operator**
BURLINGTON RESOURCES OIL & GAS COMPANY

7. **Lease Name/Unit Name**
Seymour Com A

8. **Well No.**
2

3. **Address & Phone No. of Operator**
PO Box 4289, Farmington, NM 87499 (505) 326-9700

9. **Pool Name or Wildcat**
Aztec Pictured Cliffs

4. **Location of Well, Footage, Sec., T, R, M**
800'FSL 800'FWL, Sec.36, T-30-N, R-11-W, NMPM, San Juan County

10. **Elevation:**

Type of Submission	Type of Action	
_X_ Notice of Intent	___ Abandonment	___ Change of Plans
	___ Recompletion	___ New Construction
___ Subsequent Report	___ Plugging Back	___ Non-Routine Fracturing
	___ Casing Repair	___ Water Shut off
___ Final Abandonment	___ Altering Casing	___ Conversion to Injection
	_X_ Other - restimulate	

13. Describe Proposed or Completed Operations

It is intended to restimulate the Pictured Cliffs formation of the subject well in the following manner:

Pull 1 ¼" tubing. Clean out to plug back total depth at 2257'. Acidize and foam fracture treat the Pictured Cliffs zone. Clean out and rerun tubing. Return well to production.

SIGNATURE Peggy Bradfield (MDW) Regulatory Administrator December 3, 1998

TLW

(This space for State Use)

ORIGINAL SIGNED BY CHARLIE T. PERRIN DEPUTY OIL & GAS INSPECTOR, DIST. #3

Approved by _____ Title _____ Date DEC 7 1998