

Oil / Gas / Mining

Val R. REESE, C.P.G.

Geological Consultant
900 Bank of New Mexico Building
Albuquerque, New Mexico 87101

Office: Phone 243-0665
Home: Phone 255-9749

October 5, 1970

Mr. Emery C. Arnold
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico 87410

Dear Sir:

In compliance with the Oil Conservation Commission Rule No. 111, straight hole deviation tests were made on the Riñan No. 10 well located 2400' from the north line and 1620' from the west line in Section 31 of Township 30 North, Range 16 West, NMPM, San Juan County, New Mexico, as follows:

385'	1°
670'	1/2°
890'	1/2°

The total depth of the well is 925'.

Sincerely,

Val R. Reese
VAL R. REESE



VRR:mb

STATE OF NEW MEXICO
COUNTY OF BERNALILLO

Subscribed and sworn before me this 5th day of October, 1970.

Margaret E. ...
Notary Public

My commission expires 9/25/73.