State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

		API	# (assigned by OCD)
			300452088400
Type of Well		5.	Lease Number
G AS	•	_	
		6.	
		-	E-2724-2
Name of Operator		7.	Lease Name/Unit Na
BURLINGTON			
RESOURCES OIL & GAS	COMPANY		ATLANTIC D COM 🔰 🔩
		8.	Well No.
Address & Phone No. of Operator			11
PO Box 4289, Farmington, NM 8749	9 (505) 326-9700	9.	Pool Name or Wildo
			Blanco PC
Location of Well, Footage, Sec., T			Elevation: 6559' G
800' FNL, 1600' FWL, Sec. 16, T-30	-N, R-10-W, NMPM, Sa	n Juan Count	У
Type of Submission	Type of Actio	n	
	Abandonment	Change of Pl	ans
	Recompletion	New Construc	tion
	Plugging Eack	Non-Routine	Fracturing
	Casing Repair	Water Shut o	ff
	Altering Casing	Conversion t	o Injection
<u>X</u>	Other - Restimulation	n	
1. MOL and pressure test casin	ıg.		
 MOL and pressure test casing Acidize and foam fracture to Clean out well. Return well to production. 			
 Acidize and foam fracture t Clean out well. 	reat PC zone.	EIVED C 1 4 1999	
 Acidize and foam fracture t Clean out well. 	reat PC zone.	EINES C 1 4 1999 COMPANY	
 Acidize and foam fracture t Clean out well. 	reat PC zone.	COMO EST MIN 3	

ATLANTIC D COM J # 11

Section 16 C, T-30 -N R-10 -W San Juan, New Mexico

Blanco Pictured Cliffs Field Wellbore Schematic

