6 BLM

1 NWPL. Randolph

2 El Paso

r	1	C Form Approved.				
		- Budget	Bureau	Na.	42-R142	

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Dec. 1973		
UNITE) STATES	5. LEASE
DEPARTMENT (OF THE INTERIOR	NM 10561
	CAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AN	ID REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to d reservoir. Use Form 9-331-C for such pro	oposals.)	8. FARM OR LEASE NAME 2 223
		Big Field Fig. 5 275
1. oil gas oth	er Dry Hole	9. WELL NO []
2. NAME OF OPERATOR		2
DUGAN PRODUCTION	CORP.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR		Wildcat & &
P 0 Box 208, Fari	mington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT	LOCATION CLEARLY. See space	e 17 AREA Sec. 3 T30N R14W
AT SURFACE: 790' FNL	- 1850' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:		San Juan - NM
AT TOTAL DEPTH:	NATURE OF NOT	14. API NO. E E E E E E E E E E E E E E E E E E E
16. CHECK APPROPRIATE BOX	TO INDICATE NATURE OF NOTI	
REPORT, OR OTHER DATA		15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:	

2. NAME OF OPERATOR DUGAN PRODUCTION CORP. 3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AT SURFACE: 790' FNL - 1850' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: RECEIVED TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL BUREAU OF LAND MANAGEMENTE ON Form 9-330.) PULL OR ALTER CASING MARMINGTON PESOURCE AREA MULTIPLE COMPLETE CHANGE ZONES Ready for BLM Inspection ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,

including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The #2 Big Field was plugged on 9-11-84 as per BLM stipulations as follows:

- Filled 2-7/8" OD, 6.4#, CW-55, 10 Rd. reg. tubing for casing from PBTD 1275' to surface using 35 sx class "B" neat cement.
- Installed permanent dry hole monument. 2.
- Filled all pits.
- Cleaned well location of all equipment, pipe, junk and trash.
- Restored surface per surface management agency guidelines:
- Removed tie-downs.

The location is now ready for BLM inspection.

Subsurface Safety Valve: Manu. and Type _

18. I hereby certify that the foregoing is true and correct

Geologist

no Ele

(This space for Federal or State office use)

_ TITLE APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until

herman

surface restoration is completed.