

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
API 4623495	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Texaco Inc.	8. Farm or Lease Name Schumacher
3. Address of Operator P. O. Box EE, Cortez, CO. 81321	9. Well No. 1A
4. Location of Well UNIT LETTER <u>D</u> <u>790'</u> FEET FROM THE <u>North</u> LINE AND <u>790'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>30N</u> RANGE <u>10W</u> NMPM.	10. Field and Pool, or Wildcat Blanco Mesa Verde
15. Elevation (Show whether DF, RT, GR, etc.) 6141 RKB	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Repairing Well</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/25/86: TIH W/2" impression block. Tagged stuck plunger @ 1925'. Retrieved stuck plunger. Ran broach. Found tight spots @ 470'; 1925'; 2953'; 3080'; 3770'; 4050'; 4500'; and 4869'. TOO H w/broach. TIH w/2" impression block. Tagged 1.78 ID SN @ 4978'. TOO H w/impression block. Installed plunger.

Prior to workover Q=139 MCF

After workover Q=222 MCF

RECEIVED  
APR 01 1987  
OIL CON. DIV  
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alan A. Kline TITLE AREA SUPERINTENDENT DATE 3/31/87

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE APR 01 1987

CONDITIONS OF APPROVAL, IF ANY:

NMOGCC (3) JNH-LAA-AAK-MLK