REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Dec. 1973	Budget Bureau No. 42-R1424		
UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 078626 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME San Juan 32-9 Unit		
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME San Juan 32-9 Unit		
well well other 2. NAME OF OPERATOR	9. WELL NO. 35A		
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco Mesa Verde		
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1750'S, 1680'E AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T-31-N, R-9-W N,M.P.M. 12. COUNTY OR PARISH 13. STATE San Juan New Mexico 14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

6515' GL

Haraca Continues

1 10 10 10

MULTIPLE COMPLETE CHANGE ZONES II. S. GEOLOGICAL SURVEY ABANDON* FARMINGTON, N. M. (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,

including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3650'. Ran 83 joints of 7", 20#, K-55 intermediate casing 36394-4-80: set at 3650'. Cemented w/ 369 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement 2150'.

SUBSEQUENT REPORT OF:

TD 6080', Ran 82 joints of 4 1/2". 10.5# KS casing liner 2591' set 3488-4-7-80: 6080'. Float collar set at 6063'. Cemented w/451 cu. ft. cement. 18 hours.

Subsurface Safety Valve: Manu. and Type			Set @	Ft.
18. I hereby certify that the foregoing is tru	ue and correct			
SIGNED V. S. Sucro	TITLE Drilling Clerk	_ DATE	April 11, 1980	
	(This space for Federal or State office use	·)	to have been more	\\
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE _	OIL COME	1980 1930 1931 1940 13 1940
	*See Instructions on Reverse Side			Land Company
	NIMOCO		BYE	sak-