1000

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF - 078212
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME N/A
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other	McCord 9. WELL NO.
2. NAME OF OPERATOR	7-E
Supron Energy Corp. % John H. Hill, et al	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Suite 020, Kysar Building	Basin Dakota
300 W. Arrington, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 4 T30N R13W
below.) AT SURFACE: 1000' FSL & 810' FEL (SE SE)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5701' GR
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)*
We respectfully report an error in the groun APD for the above well. Line 21 (ground ele Should be 5701' GR.	vation) shows 6394' GR.
ACC	SEPTEM FOR RECORD SOME
	APR 0.9 1991 QF JA. 3

Subsurface Safety Valve: Manu. and Type

BY

FARMINGTON DISTRICT

Set @ FAR

(This space for Federal or State office use)