

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other _____

2. NAME OF OPERATOR
OKLAHOMA OIL & GAS INC

3. ADDRESS OF OPERATOR 92660
3961 MacArthur Blvd Newport Beach Cal

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
765 Fr N Line and 2160 Fr
AT SURFACE:
AT TOP PROD. INTERVAL: East Line
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input checked="" type="checkbox"/> Spud
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other)	<input type="checkbox"/>

5. LEASE	
SF 080212	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME	
Malco Coole Sheila	
9. WELL NO.	
Shella One	
10. FIELD OR WILDCAT NAME	
Verde-Gallup	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
Sec 5 T30N R15W	
12. COUNTY OR PARISH	13. STATE
San Juan	New Mexico
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD)	
5471 GR	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded Hole June 8, 1984
Drilled 124 Hole depth of 127 Set 125 Ft 9 5/8 36 Lb new Casing
Cemented to surface with 60 sks Cl A Cement. Set tested 12 hr,
drilled depth 2545 8 3/4 hole. Set⁷ Intermediate depth 2542 ,
cemented surface 500 sks Cement . Set 24 hrs, ~~FTD~~ hole 2814.
Testing presently .
Complete open hole.

Tank Battery will be installed on the location.

7 in casing 23lb new (Intermediate string)

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Wilton E. Reeves TITLE Agent DATE June 13 1984

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

DATE
ACCEPTED FOR RECORD

JUL 02 1984

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA

RY

74MCCB