

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Foothills C	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
WC PC	
12. County	
San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	2. Name of Operator
	Joel B. Burr, Jr.
3. Address of Operator	
Suite 300, 300 W. Arrington, Farmington, NM 87401	
4. Location of Well	
UNIT LETTER <u>A</u> <u>1070</u> FEET FROM THE <u>North</u> LINE AND <u>945</u> FEET FROM THE <u>East</u> LINE, SECTION <u>14</u> TOWNSHIP <u>30N</u> RANGE <u>13E</u> <u>14W</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
5741 GR.	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-05-84 Drilled 8 3/4" hole to 75'. Ran 74.4 feet 7" casing, set at 74 feet, ground level. Cemented with 50 ^(59 cwt) sacks class B cement with 3% calcium choride and 1/4 lb. flocele per sack. Circulated 2 barrels cement to surface. Job complete 7:00 p.m. 12-05-84.

RECEIVED
DEC 12 1984
OIL CON. DIV.
DIST. 3

Report pressure test of casing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frank T. Chavez TITLE Agent DATE 12-07-84

Original Signed by FRANK T. CHAVEZ

APPROVED BY _____ TITLE _____ SUPERVISOR DISTRICT # _____ DATE DEC 12 1984

CONDITIONS OF APPROVAL, IF ANY: