	UNITED STATES TMENT OF THE INTERI		5. LEASE DESIGNATION AND SERIAL B
SUNDRY NO	TICES AND REPORTS (  POPULATION FOR PERMIT—" for such parts	ON WELLS	SF -078505  8. IF INDIAN, ALLOTTEE OR TRIBE NA
Use "APPLI	CATION FOR PERMIT—" for such pr	roposals.)	7. UNIT AGREEMENT NAME
OIL GAS WELL OTHER			N/A 8. FARM OR LEASE NAME
2. NAME OF OPERATOR  Union Texas Petroleur	m		SEYMOUR
3. ADDRESS OF OPERATOR		07401	9. WELL RO.
375   S. Highway 64 4. Location of Well (Report location See also space 17 below.) At surface	Farmington, New Mexic clearly and in accordance with any	State requirements.*	10 10. FIBLD AND FOOL, OR WILDCAT Sedro Canyon Fruitlan
	1 511		11. SUC., T., R., M., OR BLE. AND SURVEY OR ARMA
1660' FSL & 1794			Section 23-T31N-R9W
14. PERMIT NO.	15. BLEVATIONS (Show whether DF		San Juan NM
16. Check	Appropriate Box To Indicate N		
NOTICE OF INT	• •		CUENT REPORT OF:
TEST WATER SHUT-OFF FRACTURE TREAT	PULL OR ALTER CASING	- WATER SHUT-OFF FRACTURE TREATMENT	ERPAIRING WELL ALTERING CASING
SHOOT OR ACIDIZE REPAIR WELL	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZING (Other)	ABANDONMENT*
(Other)  17. DESCRIBE PROPOSED OR COMPLETED O		(Nors: Report result Completion or Recom	s of multiple completion on Well pletion Report and Log form.)
1. Drill 8-3/4" ho 2. Set 7", 23.0#, 205 sx (588 cu.	eum desires to change pole with mud out of sur K-55, ST&C casing to 3 st.) 65/35 POZ with 12 x (118 cu.ft.) Cl "B".	rface to 3245'. 3245', cementing to s 2% gel and 12-1/4# gi	urface with lsonite/sk
- 1985년 - 1985 - 1985년 - 198			
18. hereby certify that the foregoin	7 1 //		00/25/1007
SIGNED ACCEUTE	TITLE	Permit Coordinator	08/25/1987
(This space for Federal or State	office use)		
APPROVED BYCONDITIONS OF APPROVAL, II	F ANY:		DATE
	*See Instruction	is on Reverse Side	to any department on exempty of t