

HORSESHOE GALLUP #126

CURRENT WELL STATUS

History

The HGU #126 located in San Juan County, New Mexico was drilled to a depth of 1254' and completed as a Gallup oil well in June 1959. This well was converted to a water injection well in December 1962 as part of the Unit "C" secondary recovery program and was shut-in during June 1970 due to an uneconomical operation.

Existing Well Status

Casing:

Surface: 7-5/8", 24#/ft, J-55 set @ 137'
cemented to surface w/100 sx
cement.

Production: 5-1/2", 15.5#/ft, J-55 STC set @
1253' cemented w/190 sx Pozmix.

Tubing: 2-3/8", J-55 EJE 8rd

Packer: Baker 2" x 5-1/2" Model "A" type
packer set @ 1065'.

Perforations: 1093' - 1123' & 1143' - 1161' @
2 SPF within the Gallup formation.

Proposed Plugs: 1st Plug: 1040' - 1200'
2nd Plug: 850' - 950'
3rd Plug: 75' - 190'
4th Plug 0' - 30'

SMB
JEO
T.K.D.