## **LINITED STATES**

ONITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 078772
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Rosa Unit
reservoir, use rorm 9–331–C for such proposals.)	- O. TARM OR LEASE NAME
1. oil gas y other	<u>Rosa Unit</u>
well well other	9. WELL NO.
2. NAME OF OPERATOR	#91
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesa Verde
P.O. Box 90, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 1630 FNL & 970 FEL	Sec 35, T32N, R6W
AT TOP PROD. INTERVAL: Same as above	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: Same as above	Rio Arriba N.M.
34 43 420 46	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	30-039-22780
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6661 'GR
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL $\square$	(NOTE: Report results of multiple completion or zone
FOLL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	TON COM.
CHANGE ZONES	DIST. 3
ABANDON*	
(other) Drlg Operations	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	lirectionally drilled, give subsurface locations and
7 21 01 Carabant name III on (CN) (On	
7-31-81 Gearhart ran IEL, GR/SNL/CD	L. Drid to a depth of 6100'
(TD). w/ gas. Ran 74 jts (2291	$^{\circ}$ ) of 4-1/2", 10.5#, K-55, ST&
& set from 3801' to 6092' KB.	TOP of FC @ 6060'. National
cmt'ed w/ 230 sx Cl "B" w/ 4% G	el & 12-1/2# fine gils/sx
Plug displaced w/ 65 bbls wtr &	down @ 1500 hrs 7-31-81.
Reversed out 20 bbls of cmt. R	ig released @ 1930 hrs
7-31-81	•
	•
NOW WAITING ON COMPLETION.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED Nonna Deace TILE Production	Clerk 8-13-81
Donna J /Brace	
(This space for Federal or State of	fice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	

**NMOCC**