sing S g.Perf.	_@w <sup>·</sup>	Cu. ft. Sx. Int	@	SPO GL Spd. Cu. ft. Sx. Pr Prod. Siii		\	·	Sx. T		@ 	T Gas
										N S	
	BO/D _MCF/D After	Hrs. SICP.	PSI	After Days GOR _		1st De	I. <u>Oil</u>	=			
TOPS		NITD	<del></del>			TEST DATA					
Ojo Alamo		C-103	/\	Plat X	Schd.	PC	Q	PW	PD	P -	Ref.No
Kirtland		C-104		Electric Log			<u> </u>		ļ	<del> </del>	
Fruitland	<del>                                     </del>			C-122				ļ	<u> </u>	<u> </u>	<del>- </del>
Pictured Cliffs		Ditr	<u> </u>	Dfa						<u> </u>	<del></del> -
Chacra		Datr		Dac					ļ	↓	
Cliff House			1				ļ	<u> </u>	<del> </del>	<del> </del>	<del></del>
Menefee		1	$\eta = 0$	7		ļ		<del>                                     </del>	<del></del>	-	+-
Point Lookout		1				<u> </u>	ļ	<del></del>		<del></del>	<del></del> -
Mancos						ļ	ļ			<del>                                     </del>	
Gallup						<b> </b>		<del></del> -		┼	
Greenhorn						<del> </del>		<del>                                     </del>	+	+-	+-
Dakota		7			<b> </b>	ļ	<del> </del> -			+	
Entrada				W/320 Acres		<del> </del>	-	<del> </del>			1

Carracas Unit 36A #5 E-36-32N-5W

NASSAU RESOURCES, INC.



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LAPLATA HIGHWAY FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

NM-29340 et. al. (WC) 3162.3-1(F) (019)

JUN. O 6 1991

Nassau Resources, Inc. P. O. Box 809 Farmington, NM 87499

Gentlemen:

Enclosed are your Application for Permit to Drill (APD) wells Nos.:

- 1. No. 1 Carracas Unit 36A, NE/4NE/4, sec. 36, T. 32 N., R. 5 W., NM-29340.
- 2. No. 11 Carracas Unit 36B, NE/4SW/4, sec. 36, T. 32 N., R. 4 W., NM-30585
- 3. No. 1 Carracas Unit 31B, NE/4NE/4, sec. 31, T. 32 N., R. 4 W., NM-30015
- 4. No. 16 Carracas Unit 25A, SE/4SE/4, sec. 25, T. 32 N., R. 5 W., NM-59704.
- 5. No. 5 Carracas Unit 36A, SW/4NW/4, sec. 36, T. 32 N., R. 5 W., NM-59704.

Rio Arriba County, New Mexico. The subject APDs are rescinded and returned due to drilling not being commenced within two years of the approval date. (Two (2) extensions approved)

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

[s] John L. Keller

John L. Keller Chief, Branch of Mineral Resources

Enclosures

cc: New Mexico Oil Conservation Division

## ABANDONED LOCATION

