

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other instructions on reverse side.**

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMNM30584
2. Name of Operator BP AMERICA PRODUCTION CO		6. If Indian, Allottee or Tribe Name
Contact: MARY CORLEY E-Mail: corleym@bp.com		7. If Unit or CA/Agreement, Name and/or No. NMNM99460
3a. Address P. O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4491 Fx: 281.366.0700	8. Well Name and No. CARRACAS 13 B 11
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 13 T32N R4W NESW 1830FSL 1730FWL 36.98448 N Lat, 107.20839 W Lon		9. API Well No. 30-039-24649-00-S1
		10. Field and Pool, or Exploratory BASIN FRUITLAND COAL
		11. County or Parish, and State RIO ARRIBA COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Please reference telephone conversation on May 17, 2002, between representatives of BP America and Steve Mason, BLM and Charlie Perrin, NMOCD, regarding bringing various inactive wells into compliance.

BP is in the process of re-evaluating the production potential in the entire Carracas Canyon Unit. The subject well will most likely need artificial lift in order to maintain production. On 12/14/2001 we submitted a Sundry NOI of our intent to order Beam Lifts for a number of non-producing Carracas Unit wells with the intent to install after Elk Season had ended. Equipment has not arrived for installation therefore, we request additional time to finish the field wide evaluation and installation of the surface equipment necessary to restore production. In order to bring the well into compliance pending the installation of surface equipment we have proceeded to perform a casing integrity test as follows:
05/31/2002 MIRUSU NDWH & NUBOP. TOH W/prod. TBG. TIH w/CIBP & set @ 2835'. Load hole WATER &

THIS APPROVAL EXPIRES JUN 01 2003

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #11990 verified by the BLM Well Information System
For BP AMERICA PRODUCTION CO, sent to the Farmington
Committed to AFMSS for processing by Steve Mason on 06/19/2002 (02SXM0289SE)

Name (Printed/Typed) MARY CORLEY	Title AUTHORIZED REPRESENTATIVE
Signature (Electronic Submission)	Date 06/12/2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By STEPHEN MASON	Title PETROLEUM ENGINEER	Date 06/19/2002
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Office Farmington		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ****

Additional data for EC transaction #11990 that would not fit on the form

32. Additional remarks, continued

Circ hole to clear all gas & air. Pressure tested CSG to 550 PSI. Test OK. TIH w/2 3/8" TBG & land @ 2797'. RDMOSU 06/04/2002. Well TA pending further evaluation. Pressure Charts submitted to NMOCD.