


CL NASSAU

Nassau Resources, Inc.
P. O. Box 809
Farmington, NM 87499-0809
(505) 326-7793 Fax: (505) 327-0859

November 4, 1999

New Mexico Oil Conservation Division
P O Box 6429
Santa Fe, NM 87505-6429



New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, NM 87410

RE: Packer Leakage Test

Nassau plans to perform a packer-leakage test on the Carracas Unit PC #201, API #30-039-24719, located in Unit G, Sec. 22, T32N, R04W, beginning the week of November 8, 1999.

Please let us know if you plan to witness this test.

Thank you,

Fran Perrin

Fran Perrin