




July 31, 2001

DEVIATION REPORT


Well Name: ROSA UNIT #357
Location: B SEC 36 T32N R6W
County, State: RIO ARriba COUNTY, NEW MEXICO
Formation: BASIN FRUITLAND COAL

DEVIATION	DEPTH
1/4°	265'
3/4°	788'
3/4°	1258'
3/4°	1765'
1°	2254'
1°	2727'



Tracy Ross
Production Analyst

State of Oklahoma)
County of Tulsa) ss:

The foregoing instrument was acknowledged before me this 31st day of July, 2001, by Tracy Ross.



Susan A. Tyler

My Commission Expires: 7-17-2005






CROSS TIMBERS OPERAT ; COMPANY
 CHAVEZ GAS COM "C" #1M, 1235' FSL 740' FWL
 SECTION 23, T29N, R10W, N.M.P.M., SAN JUAN COUNTY, N.M.
 GROUND ELEVATION: 5599', DATE: FEBRUARY 26, 2001

LAT. = 36°42'29" N.
 LONG. = 107°51'39" W.



RESERVE PIT DIKE: TO BE 8' ABOVE DEEP SIDE (OVERFLOW - 3' WIDE AND 1' ABOVE SHALLOW SIDE).
 BLOW PIT: OVERFLOW PIPE HALFWAY BETWEEN TOP AND BOTTOM AND TO EXTEND OVER PLASTIC LINER AND INTO BLOW PIT.



NOTE: CONTRACTOR SHOULD CALL ONE-CALL FOR LOCATION OF ANY MARKED OR UNMARKED BURIED PIPELINES OR CABLES ON WELL PAD AND OR ACCESS ROAD AT LEAST TWO (2) WORKING DAYS PRIOR TO CONSTRUCTION.

DRAWN BY: B.S. ROW#: CR027 CADFILE: CR027CF8 DATE: 3/07/01

Daggett Enterprises, Inc.
 Surveying and Oil Field Services
 P. O. Box 15068 Farmington, NM 87401
 Phone (505) 326-1777 Fax (505) 326-6019