



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Santa Fe
Lease No. 1M 01014
Unit Thompson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 15, 1962

Thompson
Well No. 7-1 is located 990 ft. from 1/4 line and 1110 ft. from Ex line of sec. 34

Section 34 (1/4 Sec. and Sec. No.) T-31N (Twp.) R-12W (Range) N.M.P.M. (Meridian)
Basin Dakota (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5015 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.B.D.D. - 7000'
sand-water fraced with 57,000 gals. water, 50,000 lb sand
breakdown pr. - 2200
avg. treating pr. - 2300
con. treating pr. - 3000
avg. I.R. - 34.7 bpm
dropped 100 rubber ball sealers
flushed with 120 Bbls.
ran 215 jts., 6005' of 2 3/8" tubing, landed at 6815'
shut in for gauge.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Enter Oil and Gas Company

Address Drawer # 570

Farmington, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON
By Joe C. Salmon
Title District Superintendent