

**(SUBMIT IN TRIPLICATE)**

Indian Agency Navajo Ute

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. 14-20-604-1951

	X		

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<b>Sandoll Frac.</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 8 1958

## Horseshoe Ute

Well No. 10 is located 660 ft. from S line and 1930 ft. from W line of sec. 34

**SE SW/4 Sec. 34**

**31N**

**16W**

**NMPM**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

## Horseman Gallup

## San Juan

## New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5497 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**12-7-58 Total Depth 1520'. Clean Out Total Depth 1461'.**

Sandoil fractured Lower Gallup perforated intervals 1347'-82' (perf. 2 in./ft.) with 29,400 gals. oil and 28,000# sand. BDP-900#, MTP-800#, ATP's-700-800. Injection Rate--49.4 Bbls./Min. Flush 1470 gals. oil. Dropped 35 rubber balls one time.



**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company **El Paso Natural Gas Products Company**

Address Post Office Box 1565

**Farmington, New Mexico**

ORIGINAL SIGNED BY: JOSEPH E. KREGER  
By \_\_\_\_\_

Title Petroleum Engineer