

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved: **50101 P8.**

Land Office **053622 H.M.**

Lease No. **I**

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 30


62

1 **1565** **XXXX** **1050** **XXX** **31**
Well No. **S.E. 31** is located **31N** ft. from **{N}** line and **NMPH** ft. from **{E}** line of sec. **31**
Basin Dakota **San Juan** **New Mexico**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian) (State or Territory)
5700 **C.L.**

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

Drilled 1908 12 1/4 Hole Set 180' 8 1/2" 24" 35 cemented 4
150 Sks cement 2% H.A. 5 Woe 24 hr Pres to 500# Held OK



I understand that this work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **402 Philtower Bldg**

Add **Elisa, Okla.**

By **W. H. Harrow**
Agent

Title _____