

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Ute Mountain Tribal

Allottee _____

Lease No. 14-20-604-29

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ute Mountain Tribal

Farmington, New Mexico July 23, 19 57

Well No. 2 is located 2125 ft. from N line and 660 ft. from W line of sec. 33

NW 1/4 of Section 33
(1/4 Sec. and Sec. No.)

T-31-N

R-15-W

N.M.P.M.

Verde-Gallup

San Juan

(Meridian)

(Field)

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 5575 ft. (Ground level)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was spudded on June 22, 1957, and on June 23, 1957, 8-5/8" casing was set at 255' with 170 sacks of cement. After waiting on cement for 24 hours, casing and water shut off were tested with 400 pounds pressure with no drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations can be commenced.

Company Pan American Petroleum Corporation

Address Box 487

Farmington, New Mexico

By [Signature]

Title Field Clerk

7

