

(SUBMIT IN TRIPLICATE)

Indian Agency _____

Ute Mountain Tribal

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Allottee _____

Lease No. **14-20-604-89**

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

AUG 30 1961

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	X
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ute Mountain Tribal "A"

Farmington, New Mexico

August 25, 19 61

Well No. **2** is located **2125** ft. from **[N]** line and **660** ft. from **[W]** line of sec. **33**

SW/4 NW/4 of Section 33 T-31-N R-15-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Verde Gallup San Juan
(Field) (County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5575** ft. (GL)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As a result of the above well ceasing to produce oil in commercial quantities,
We have plugged and abandoned it as follows:

1. Moved in pulling unit and pulled rods and tubing.
2. Re-ran tubing with fishing tool and recovered 4" liner (uncemented) set 2504-2678 with perforations located at 2566-2631 (details on liner above).
3. Spotted 40 sacks cement plug on bottom and 40 sacks of cement plug from 2680' to 2300'.
4. Filled hole with fluid
5. Pumped 25 sacks cement plugged down 5-1/2" - 8-5/8" annulus
6. Removed wellhead and surface equipment.
7. Spotted 5 sacks cement plug for surface plug and erected abandonment marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Pan American Petroleum Corporation**

Address **P. O. Box 480, Farmington, New Mexico**

Attn: **L. O. Speer, Jr.**

ORIGINAL SIGNED BY

By **L. O. Speer, Jr.**

Title **Area Superintendent**

