

(SUBMIT IN TRIPLICATE)

Indian Agency

Nov.-95


UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee

Lease No.

14-80-604-1951

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Plugging back through Dakota	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 22

19 58

Well No. Ute No. 2 is located 2140 ft. from S line and 735 ft. from W line of sec. 34  
NW 1/4 Sec. 34 11N 10W 104N  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Verde Valley San Juan New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5375 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled through Dakota. Total Depth 2050 feet. No shows of oil or gas.

25 foot plug placed at 2025-2050', 25 foot plug from 1815'-1840'.

7" casing set at 1304.78'.

25 foot plug placed at 1304.78'-1329'.

Top Dakota 1840'

15 sacks cement used on each plug.

Top Morrison 2045'

7-7/8" hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Banner Drilling Company

Address Box 1571

Farmington

New Mexico

By

Ben Banner

Title

Co-Owner

