## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

instructions in the Rules and Regulations	of the Commission.  Indicate Nature of Repo	rt by Checking Be	low	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESUL	T OF TEST	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOR	MPLETION	REPORT ON (Other) Corrected	Location X
	(Date)	May 6, 1953	Farmington	New Mexico
Following is a report on the work	done and the results obtained	under tne heading r	noted above at the	
El Pago No (Company or Ope	tural Gas Comeny		Atlantic State	
· -	tural Gas Company	Well No2	in the 1/4 NE	½ of S.36
T31N, R10W, NMPM.,		Pool,	San Juan	County
The Dates of this work were as folows:	May 6, 19	53		
Notice of intention to do the work (was)				
and approval of the proposed plan (was)			(Cross out incorrect words)	
	LED ACCOUNT OF WORK I	OONE AND RESU	LTS OBTAINED	
	f this well has been North line and 1114 31N, R-10W.		ast line of	COM. COM.
Witnessed by	El Peso	Natural Cas (Company)	Company Geologia	, <b>t</b>
Approved: OIL CONSERVATION	COMMISSION	I hereby certify the to the best of my	at the information given above	is true and complete
(Name)	Juni Ed	Name	(15)	***************************************
V			roleum Engineer L. Paso Natural Gas C	copeny
Oil and Gas Inspector Dis	$\frac{1.42}{\text{(Date)}}$	•	r-997-Farmington, No	

COMPANY	EL PA	SO NA	TUPAL	GAS CO	PALY		······································		
Well Name &	No		Atlant	<u>ic -</u> S	tate N	0, 2		Leas	se No.
Location 111	4 feet	from	the Ea	st lin	e. 1776	5 foot	from	the No	rth line.
Being in $SE_{\frac{1}{4}}$ of the $NE_{\frac{1}{4}}^2$									
Sec. 36, T31 N., R10 W., N.M.P.M., San Juan County, New Mexico									
Ground Elevation 6634.54									
					ļ	,	,		
			— — i				7776'		
								1114'	
				Secti	on 36				N
					j				
								! !	
		Sca	ale	4 inc	hes equ	uals l	mile	J	
Surveyed		)/ <sub>2</sub>	<b>y</b> 4						, 19 <u>53</u>
This is to actual surv true and co	eys mad	e by n	ne or	under	my supe	ervisi	on and	that '	eld notes of the same are
Seal:									ofessional Land Surveyor.

Farmington, New Mexico

Note: This plat is to correct footage of the location as well was originally located from rock mound which was not the section corner.

OIL CONSERVATION AZTEC DISTINO Copies Received	RICT OFFICE ad <b>3</b> 5	SION
	NO.	
	FURNISHED	
Operator		
Santa Fe		
Proration Office		
State Land Office	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
U. S. G. S.	2	
Transporter		
File		/