


(SUBMIT IN TRIPLICATE)

Indian Agent **SAV. 1328**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease **14-20-604-1951**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED

NOV 16 1958

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON NEW MEXICO

November 5th, 1958

Well No. **3** is located **210** ft. from **N** line and **390** ft. from **E** line of sec. **33**
N.E. 1/4 **216.33** **31N** **16W** **21N1E**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Horse Shoe Allup Ent. **San Juan** **New Mex.**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5733** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SPUDDATE 10/22-58 10/23-58 T.D. 125 ft.
 Run 4 Joints - 8 3/8 240 J - 95 CS.
 (119.12') Set at 122 ft. with 100 sacks Ce. Cement circulated
 to surface Hold 500 #/30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Banner Drilling Co.**

Address **P.O. Box 1571**

Farmington, New Mex.

By **Ben Banner**

Title **Co-owner**