

(SUBMIT IN TRIPLICATE)


UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_

Ute Navajo

Allottee \_\_\_\_\_

Lease No. 14-22-60-1971



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

9-27

1959

Well No. 5 is located 1670 ft. from N line and 330 ft. from W line of sec. \_\_\_\_\_

27

11N

16W

104N

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Hereshee Gallup

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 7620 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-27-59  
9-28-59

Spud  
2.2, 70; Set 2 1/2, 3-75, 8 5/8" casing @ 71.70,  
w/ cement cement, Circulated cement.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Petro Atlas Inc.

Address P.O. Box 1976

Farmington, New Mexico

By [Signature]

Title Gept.

Handwritten text, possibly a signature or date, located in the lower-left quadrant of the page.

Small handwritten mark or signature at the bottom center of the page.