

(SUBMIT IN TRIPLICATE)

Indian Agency Ute Mountain

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_  
Lease No. 14-20-604-88

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL..... <b>XX</b>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 6, 1963

Well No. C-1 is located 1700 ft. from XXX line and 1990 ft. from E line of sec. 27  
N4/4 SE/4 Sec 27 31N 15W 10PM  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Verde Gallup San Juan New Mexico  
 (Field) (County or Subdivision) (State or Territory)



The elevation of the ground level ~~bottom hole~~ above sea level is 5560 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plan to Plug well as follows:

- (1) Spot 20 sz cement 2775' to 2600'.
- (2) Spot 25 sz cement at top stub 50' in stub and 50' in open hole.
- (3) Spot 34 sz cement 900' to 1000'.
- (4) Spot 5 sz bottom surface seg.
- (5) Spot 5 sz top surface seg.
- (6) Erect dry hole marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lipan Oil Company

Address P.O. Box 1071

San Angelo, Texas

By Original signed by T. A. Dugan

Title Consulting Engineer

U.S. GEOLOGICAL SURVEY  
DURANGO, COLO.