

Form 8-881b
(9-1-1962)

APPROVED

APR 29 1965

E. A. SCHMIDT
ACTING DISTRICT ENGINEER

State

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R359.4.

Indian Agency _____
Allottee _____
Lease No. **24-20-604-88**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 27, 1963

Well No. **Ute** is located **1700** ft. from **SW** line and **1990** ft. from **E** line of sec. **27**

SW 1/4 Sec 27 (1/4 Sec. and Sec. No.) **31N** (Twp.) **15W** (Range) **112PM** (Meridian)

Verde Canyon (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the ~~surface~~ **ground level** above sea level is **5560** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged well as follows:

- (1) Spotted 20 sz cement 2775' to 2600'
- (2) Spotted 25 sz cement 1485' to 1535'
- (3) Spotted 34 sz cement 900' to 1000'
- (4) Spotted 5 sz bottom surface csg.
- (5) Spotted 5 sz top of surface csg.
- (6) Erected dry hole marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Ute Oil Company**

Address **P.O. Box 1071**

San Angelo, Texas

By **Original signed by T. A. Dugan**

Title **Consulting Engineer**