

Form 9-381b
(April 1952)

(SUBMIT IN TRIPLICATE)

Indian Agency _____

Navajo - Ute Mtn. Tribal

Allottee _____

Lease No. 14-20-604-1951UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of casing	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 15, 19 63


Horseshoe Gallup Unit
Well No. 158 is located 1740 ft. from [N] line and 590 ft. from [W] line of sec. 28NM/4 Sec. 28 31N 16W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Horseshoe Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 5666 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well at 10:30 am 12-23-62. Ran 8 5/8" O.D. 28# J-55 casing set at 76.30'. Cemented with 60 ex cement plus 2% CaCl. Plug down at 5:30 pm 12-23-62. Cement circulated.

W.O.C. & rig repair 78 hrs. Tested 8 5/8" casing with 700 psi for 30 min. OK Started drilling with air at 8:00 pm 12-26-62.

RECEIVED
FEB 14 1963
U. S. GEOLOGICAL SURVEY
TERRITORY, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE ATLANTIC REFINING CO.Address BOX 2197Farlington, N.M.By B. J. SartainTitle Drilling & Prod. Supervisor

11-20-64-1-1981

Subsequent Report of casing

February 12

58

X

220

X

1780

Horrocks Gullup Unit

178

11114

101

311

11114 SW 1/4 Sec. 28

New Weston

San Juan

Horrocks Gullup

5855

Spotted well at 10:30 am 12-23-62. Run 2 5/8" O.D. 116 1-2" casing set at 7:30 PM. Cemented with 60 ex cement plus 25 Gell. Plug down at 2:30 pm 12-23-62. Cement circulated.

4000 ft. & rig repair 76 hrs. Worked 2 5/8" casing with 700 feet for 30 min. CE started drilling with air at 8:00 pm 12-26-62.

THE ATLANTIC REFINING CO.

BOX 2127

Washington, N.M.

E. J. Johnson

Drilling & Prod. Supervisor