June 1990)	DEPARTMEN	TED STATES T OF THE INTERIOR AND MANAGEMENT	FORM APPROVED Budget Buresu No. 1004-0135 Expiret: March 31, 1993 5. Lesse Designation and Serial No.
Do not use this form	n for proposals to dri	AND REPORTS ON WELLS If or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	14-20-604-1951 6. If Indian, Allottee or Tribe Name Ute
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Achier Water Injection Well 2. Name of Operator			Horseshoe Gallup 8. Well Name and No. HGU #169
Vantage Point Operating Company 3. Address and Telephone No.			9. API Well No. 30-045-42641/0335
2401 Founts 4. Location of Well (Footspe.	ain View Dr., Sec., T., R., M., or Survey De	Suite 700, Houston, TX 77057	10. Field and Pool or Exploratory Area Horseshoe Gallup 11. County or Parish, State
	6W, 660' FSL		San Juan, New Mexic
· · · · · · · · · · · · · · · · · · ·		5) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SL	TYPE OF SUBMISSION TYPE OF ACTION		
Notice of It		Abendomment Recompletion Plugging Back Casing Repair Altering Casing Other MIT, LTSI	Change of Plans New Construction Non-Routine Fracturing Water Statt-Off Conversion to Injection Dispose Water (Note: Report results of authiple completion on Wed Completion or Recompletion Report and Log form.)
		l pertinent details, and give pertinent dates, including estimated date of starti at depths for all markers and zones pertinent to this work.)*	ing any proposed work. If well is directionally drilled,
10-07-91	Pressure test in pressure i	ted casing-tubing annulus to l in 15 minutes. Witnessed by l	400 psi with no loss D. Foust/NMOCD.
Vantage wo	uld like to m well until it	rice of oil and current econor maintain long term shut-in sta is economically feasible to	atus of the above

Consulting Engineer

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

CONDITIONS OF APPROVAL:

This Shut-In approval is contingent upon conducting a casing integrity test by OCT 0 7 1994. Mark Kelly with the Farmington Office is to be notified at least 48 hours prior to conducting the casing integrity test (505-599-8907). If the casing test fails, you will be required to submit your plans to repair the casing or plug and abandon the well.

Office Hours: 7:45 a.m. to 4:30 p.m.