

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Ute Mountain Tribal

Allottee _____

Lease No. 14-20-604-84

		X
	30	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	X
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER WORK DONE)
OCT 10 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON NEW MEXICO

October 9


Well No. 31 is located 610 ft. from N line and 1965 ft. from E line of sec. 30
NW NE Sec. 30 11N 11W NMPN
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde-Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5590 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded with rotary tools 4:15 p.m. 10-6-58. Drilled 12-1/4" hole to 115 feet. Ran 4 jts. 106.87 feet 8-5/8" 2 1/2" casing set at 115 feet K.B. w/120 sz. regular cement 2% calcium chloride. Cement circulated. Plug down 6:30 a.m. 10-7-58, WOC 2 1/2 hours. Tested plug w/900 PSI for 30 mins. Test OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Three States Natural Gas Company

Address P. O. Box 67

Farmington, New Mexico

By _____

Title District Superintendent

