

(SUBMIT IN TRIPLICATE)

Indian Agency **Law-010**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No. **14-20-604-1951**

			X

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 18, 19**59**

Well No. **8** is located **530** ft. from **N** line and **500** ft. from **E** line of sec. **28**

12-02-20 **31N** **16W** **114PM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Horse Shoe Canyon **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5466** ft. **GL.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate cementing jobs, cementing points, and all other important proposed work)

Spud Date **8/22/59** **112'**
Run **4 Jts 8 & 240 & 55 (CSO 101')**
Set at **100' W/100 sacks Reg Cement**
Circulated to surface, Held **500# 90 Minutes**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Banner Drilling Company**

Address **P. O. Box 1571**

Farmington, New Mexico

By **Ben Banner**

Title **Co-Owner**

