


(SUBMIT IN TRIPLICATE)

Indian Agency Isauro

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 21-20-601-62



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 10, 1959

Well No. 7-6

Well No. 7 is located 1720 ft. from S line and 660 ft. from E line of sec. 20

NE/4 Sec. 20
(1/4 Sec. and Sec. No.)

T-11-N
(Twp.)

R-11-E
(Range)

S. 1. 1. 1.
(Meridian)

Varian Gallup
(Field)

San Juan County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5625 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 6/25/59. Set 3 joints, 89', of 7 1/8" casing at 96' with 90 sz. cement.

Tested casing with 500# pressure for 30 minutes, no leaks.

Filled cement plug 6/27/59. Tested for 30 minutes with 500# pressure, no drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ARTEC OIL & GAS COMPANY

Address Box 786

FARMINGTON, NEW MEXICO

By ORIGINAL SIGNED BY JOE C. SALMON

Title DISTRICT SUPERVISOR