

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Window Rock

Allottee Navajo Mtn. Tribal

Lease No. 14-20-600-3531

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		
	Perforate-Treat	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 10, 19 59

Well No. 3 is located 660 ft. from [S] line and 660 ft. from [E] line of sec. 19

Horseshoe Gallup
(1/4 Sec. and Sec. No.)

31 N
(Twp.)

16 W
(Range)

N.M.P.M.
(Meridian)

SE SE Sec. 19
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the d... above sea level is 5505 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran Gamma Ray Correlation Log to 1442', their FBD. Perforated 1290-1304' Schlumberger = 1292-1306' Gamma Ray with 56 jets. Treated perforations with 50,000# 10/20 sand and 15,876 gallons lease crude. Formation broke down 2200# to 1700#. Average injection pressure 1300# at 32.5 BPM. Job complete 12:30 P.M., 3-8-59.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Atlantic Refining Company

Address P. O. Box 520

Gasper, Wyoming

By B. J. Sartain

Title Dist. Drilling Supt.

