

Sec 21

(SUBMIT IN TRIPLICATE)

Indian Agency **Consolidated Ute**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allotted **14-20-604-83**

Lease No. **Ute Mountain**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEP 14 1959
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

September 10, 1959

Well No. 7 is located 1980 ft. from 31 [S] line and 1980 ft. from 14 [W] line of sec. 21
SW/4 Sec. 21 31 N 14 W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~drill~~ floor above sea level is 5623 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 5 jts 104' of 8 5/8" cas. @ 115' w/100 sks + 2% cact, cement circulated
5:30 p.m., 9-7-59 - Test 8 5/8" cas w/700# 30 min. Hold O.K.

Spud at 1:00 a.m., 9-7-59.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Magnolia Petroleum Company

Address Box 2106

Hobbs, New Mexico

By [Signature]
Title District Superintendent

