

(SUBMIT IN TRIPLICATE)

Indian Agency Ute Indian

UNITED STATES


Ute Mountain

DEPARTMENT OF THE INTERIOR

Allottee 11-20-60-123

GEOLOGICAL SURVEY

Lease No. _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 22

Well No. 1-23 is located 2910 ft. from [N] line and 1835 ft. from [E] line of sec. 23


Ute Indian (Name)
Verde Canyon (Road)
San Juan (County or Subdivision)
New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5563 ft. L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 1/15/58. Set 128.77 ft. 10 3/4" 32.75 lb/ft casing.
Casing set with 60 sacks regular cement 1/15/58. Drilled plug and
tested with 1200 psi 1/16/58.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GREENHORN OIL CO.

Address Dart Building

1700 Patterson Street

Dallas, Texas

By Paul J. Harte

Title Drilling Superintendent