



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Ute Mountain

Tribal Lands

Allottee

Lease No.

Contract 14-20-604-87

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
JAN 20 1964
U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 14, 1964

Ute Mountain Tribe "A"
Well No. 6 is located 2310 ft. from SW line and 330 ft. from E line of sec. 22

SE 1/4 Section 22 31 N 15 W NMPM
(A Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Verde Canyon San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ground level ~~surface~~ above sea level is 5595 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We request permission to remove all equipment, pull casing, plug and abandon well.

1. Plug 2200 - TD 2331
 2. 100' plug on 5 1/2" casing stub 1650 - 1750
 3. 100' plug 950- 1050 across top of Mancos
 4. 50' plug 75 - 125 on 8 5/8" shoe
 5. 105 x at surface w/marker
- Heavy mud between plugs.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C & S Casing Pulling Service

Address Box 778

Craig, Colorado

William F. Rippey
Title Partner