

X			
	22		



(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency Consolidated Ute.

Allottee 14-20-604-83

Lease No. Ute Mountain

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 22, 1960

Well No. 13 is located 1980 ft. from N line and 660 ft. from W line of sec. 22

<u>NW 1/4 Sec. 22</u> (1/4 Sec. and Sec. No.)	<u>31N</u> (Twp.)	<u>14W</u> (Range)	<u>NMB&amp;M</u> (Meridian)
<u>Verde-Gallup</u> (Field)	<u>San Juan</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)	

The elevation of the ~~derrick floor~~ <sup>G.L.</sup> above sea level is 5613 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 2 PM, 8/19/60.

Cemented 5 joints, 101' of 8-5/8", 29# lapweld casing at 108' w/80 ax. + 2% CaCl. Circulated cement.

Plug down 8 PM, 8/19/60. Tested w/700 psi for 30 min., ok.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Socony Mobil Oil Company, Inc.

Address Box 3371

Durango, Colorado

By P. M. Barry

Title Dist. Prod. Supt.



RECEIVED

JAN 14 1960

U. S. GEOLOGICAL SURVEY  
BOSTON, MASS.