

Sec. 21

(SUBMIT IN TRIPLICATE)

Consolidated Ute

Indian Agency

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee #14-20-604-83

Lease No. Ute Mountain

		6	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	1
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	AUG 20 1959
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

August 17, 1959

Well No. 6 is located 1980 ft. from N line and 1980 ft. from E line of sec. 21

NE/4 Sec. 21 (1/4 Sec. and Sec. No.) 31N (Twp.) 14W (Range) N.M.P.M. (Meridian)

Verde Gallup (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ~~surface~~ G.L. above sea level is 2561 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 5 jts. 102' of 8-5/8" cas. @ 102' w/100 lbs. neat cement circulated PD @ 7:15 p.m. 8-14-59. Test 8-5/8" w/700# 30 min., O.K.

Spudded 1 a.m. 8-14-59.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Magnolia Petroleum Company

Address Box 2406  
Hobbs, New Mexico

By [Signature]  
Title District Superintendent