


(SUBMIT IN TRIPLICATE)

Indian Agency Tenneco

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No. 11-30-00-121



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 7 is located 100 ft. from N line and 100 ft. from W line of sec. 23
34/36, Section 23 1-23-4 23-4 23-4
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Farmer San Juan County New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5225 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 2633. Can logs: Top of the Lower Gallup-2552.

Sandwell fraced open hole 2552-2633, with 1000 bbls. oil and 10,000 gal. water. Treating pressure-10700, Final pressure-2000, I. A. 10 bbls.

Landed 2527' of 2 1/2" tubing at 2528'. Installed pump and rods.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ATOMIC OIL & GAS COMPANY

Address Box 706

Farmer, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON

Title DISTRICT SUPERVISOR